


Co/C
00862.022227.1

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Hiroshi KUROSAWA)	:
Application No.: 10/676,156)	Examiner: R. E. Fuller
Filed: October 2, 2003)	:
For: EXPOSURE APPARATUS, MAINTENANCE METHOD THEREFOR, SEMICONDUCTOR DEVICE MANUFACTURING METHOD, AND SEMICONDUCTOR MANUFACTURING FACTORY)	Group Art Unit: 2851
U.S. Patent No. 6,940,584 B2)	:
Issued: September 6, 2005)	November 16, 2005

*Certificate
NOV 21 2005
of Correction*

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
Attention: Certificate of Correction Branch

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULE 323

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a minor nature which are not the fault of the U.S. Patent and Trademark Office.

11/17/2005 CNGUYEN 00000075 6940584

01 FC:1811


100.00 OP

NOV 22 2005

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Attorney for Patentee
Steven E. Warner
Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
SEW/eab

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,940,584 B2

DATED : September 6, 2005

INVENTOR(S): Hiroshi KUROSAWA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS:

In "Sheet 4 of 15," "FIG. 4," in the box immediately left of box "410", "RERY" should read -- RETRY --.

COLUMN 3:

Line 3, "during" should read -- during a --.

COLUMN 5:

Line 30, "107" should read -- 107, --.

Line 60, "locus" should read -- focus --.

COLUMN 7:

Line 55, "starts" should read -- start --.

COLUMN 11:

Line 34, "factor" should read -- factory --.

Line 64, "a" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,940,584 B2

No. of add'l. copies
@ 30¢ per page

